

Case History #104

North America's premier waterproof vinyl flooring systems. Since 1974.

Project:

Oak Lane Apartments

Forrest Lane

Dallas, Texas

Date:

Spring 1982





Problem:

In the spring of 1982, the **Duradek** applicating contractor had repaired 30,000 sq. ft. of balconies, walkways and stairs of a thirteen building apartment project. There was massive sub-structure damage due to water leakage through the lightweight concrete decking. Over 50% of the total area was rotten, creating a serious safety hazard.

Recently, the contractor was called in to do minor repairs. There were small tears where heavy appliances had been moved and some general wear on the heavy-traffic landing areas.

Duradek Solution:

Duradek Classic (20 mil). After major repairs were done to the rotten substructure, the contractor waterproofed the original 30,000 sq. ft. project with Duradek. When called in years later, the contractor easily repaired the small tears, replaced the worn landings and pressure-washed the entire surface to bring back the appearance and non-skid texture (hidden under dirt).

Applicating Contractor:

Surface Systems & Associates P.O. Box 6742 Branson, MO 65615 (417) 561-8102

Job Contact:

Mitch Owens-Fultz Management 300 Crescent Court, 12th Floor, Dallas TX 75201 (214) 871-6677

Job Notes:

Maintenance costs for property owner after eleven plus years was \$5500. There has been no further rot or sub-surface damage.

For more information about the complete Duradek product line call (604) 591-5594 or fax (604) 591-3100