

Case History #106



North America's premier
waterproof vinyl flooring
systems. Since 1974.

Project:

Mel Tillis Theatre
Branson Inn
Branson, MO

Date:

Fall 1993



Problem:

A newly constructed four-storey addition to the existing Inn had already experienced leaks on the outer edges of the hollow core balcony slabs where the concrete slabs had many cracks. Previous attempts to waterproof the surface with liquid sealants proved unsuccessful. The owners were concerned about the long term effects of water penetration on the concrete and metal structure as well as the appearance.

Duradek Solution:

**DURADEK ULTRA
STEEL (60 mil).**

Surface cracks were filled with a polymer grout. The concrete was broom finished and needed grinding to smooth it down. The vinyl was applied with a contact type adhesive. The perimeters were secured with "L" trim to both the steel fascia and the brick wall.

Applicating Contractor:

Surface Systems & Associated
Branson, MO 65616
(417) 561-8102 Fax: (417) 561-2202

Job Notes:

Job size 5,000 sq. ft.

**For more information about the complete
Duradek product line call (604) 591-5594
or fax (604) 591-3100**

